

Commands for Creating an HUS Report

What We Need


Output Specifications from your device to quote and onboard your spare.

Why This Matters


Learn what happens with the outputs retrieved and why we need the information from these commands at [PIVIT's Sparring Integrity Program](#).

Procedure


Step 1




Step 2: Select C: drive




Step 3: Select DKC200




Step 4: Copy the config file to your local PC



Step 5: Create a local directory on your laptop and copy the directory here



Step 6: Compress the file, then email the compressed file to onecall@pivtglobal.com



Share file with OneCall Support: <https://onecall.pivtglobal.com/file-upload/quote>